



REPLACEMENT FOR

ESTIMA '00



REPLACEMENT FOR

FORTUNER '04



212-11C2
HEAD LAMP
R 81130-28570
L 81170-28570
PCS CFT



H7/PY21W TBA



212-11H8- RD LD
HEAD LAMP
RD:
R 81105-0K100
L 81106-0K100
PCS CFT
LD:
R 81105-0K110
L 81106-0K110
R 81110-0K110
L 81150-0K110



HB4/HB3/PY21W/W5W TBA

212-19D3-YR
TAIL LAMP
R 81551-28260
L 81561-28260
PCS CFT



TBA



212-2047
FOG LAMP
R 81210-0K050
L 81220-0K050
PCS CFT



HB4 TBA

212-19D3
TAIL LAMP
R 81551-28270
L 81561-28270
PCS CFT



TBA

212-1312 BACK LAMP
R 81581-28090
L 81591-28090
PCS CFT



TBA

212-19L7
TAIL LAMP
R 81551-0K070
L 81561-0K070
R 81550-0K070
L 81560-0K070
PCS CFT



P21/5W TBA

212-19D3-CR
TAIL LAMP
R 81551-28300
L 81561-28300
PCS CFT



TBA

212-1312-CR BACK LAMP
R 81581-28050
L 81591-28050
PCS CFT



TBA

212-1323 BACK LAMP
R 81581-0K010
L 81591-0K010
PCS CFT
R 81580-0K010
L 81590-0K010





W5W/P21W TBA

212-2917
REFLECTOR
76801-28070
PCS CFT



TBA



TOYOTA