



REPLACEMENT FOR
SPORTAGE '95-'97



REPLACEMENT FOR
SPORTAGE '98




REPLACEMENT FOR
SPORTAGE '05-'06

223-1110
HEAD LAMP
R
L



H4 PCS CFT **TBA**

223-1108-M
HEAD LAMP
R
L



H4 PCS CFT **TBA**

223-1120-LD-EM
HEAD LAMP
R 92101-1FOR
L 92101-1FOL
L 92101-1F021
PCS
CFT



H4/PY21W/W5W **TBA**

223-1506
CORNER LAMP
R
L



PY21W PCS CFT **TBA**

223-1505
CORNER LAMP
R
L



PY21W PCS CFT **TBA**

223-1120-LD-E
HEAD LAMP
R 92102-1F010
L 92101-1F010
PCS
CFT



H4/PY21W/W5W **TBA**

223-1906
TAIL LAMP
R
L



TBA

323-1904
TAIL LAMP
R
L 0K080-51-160
PCS CFT



12V21/5W/12V21/5W/12V21W **TBA**

323-2009-UED
FOG LAMP
R 92202-1F000
L 92201-1F000
R 92202-1F001
L 92201-1F001
PCS CFT



TBA

223-1919-A/U
TAIL LAMP
R 92401-1F010
L 92402-1F010
L 92401-1F030
PCS
CFT



27/8W/27/8W/W1.6W **TBA**

323-1919-AS
TAIL LAMP
R 92402-1F020
L 92401-1F020
PCS
CFT



TBA



REPLACEMENT FOR

SPORTAGE '98-'02 U.S.A TYPE

323-1105-AS

HEAD LAMP
R OK08A-51-030B
L OK08A-51-040B
6PCS
5.6CFT



H4

323-1501-DS

CORNER LAMP
R OK08A-51-060
L OK08A-51-070
20PCS
4.73CFT



P21W

323-1501-NS

CORNER LAMP
R OK08A-51-060B
L OK08A-51-070B
20PCS
4.73CFT



P21W

323-1904

TAIL LAMP
R
L OK080-51-160
PCS CFT



12V21/5W/12V21/5W/12V21W

TBA

