

LADA



REPLACEMENT FOR

2105/2106/2107 '83-'88

REPLACEMENT FOR

2108 SAMARA '86-'90

662-1104-LD 2105 43T
 HEAD LAMP
 R 2105-3711010-10
 L 2105-3711011-10
 6PCS 5.60CFT



662-1103-LD 2107 43T
 HEAD LAMP LD:
 RD: R 2107-3711010-11
 R 2107-3711010-10 L 2107-3711011-11
 L 2107-3711011-10 6PCS 5.60CFT



662-1101-LDEHU 43T
 HEAD LAMP
 R
 L
 6PCS 6.28CFT



H4/T4W/P21W

662-1401
 SIDE LAMP
 R
 L
 PCS CFT



TBA

662-1101-LD-E 43T
 HEAD LAMP
 R 2108-3711010-01
 L 2108-3711011-01
 6PCS 6.28CFT



H4/T4W

662-1902 2105
 TAIL LAMP
 R
 L
 10PCS CFT



TBA

662-1901 2107
 TAIL LAMP
 R
 L
 PCS CFT



TBA

662-1501-UE
 CORNER LAMP
 R
 L
 50PCS 4.57CFT



P21W

662-1903 NIVA 1600CC 2106
 TAIL LAMP
 R 2105-3716010-01
 L 2105-3716011-01
 PCS CFT



TBA

662-1910 2104
 TAIL LAMP
 R
 L
 PCS CFT



TBA



LADA