

REPLACEMENT FOR

**bB '00**

**212-11B6**  
 HEAD LAMP  
 R 8110-52090  
 L 81150-52090  
 PCS CFT



H4/WY21W/W5W TBA

**212-2023**  
 FOG LAMP  
 R 81210-52020  
 L 81220-52020  
 PCS CFT



TBA

**212-1419** bB/LS430  
 SIDE LAMP  
 81730-53010  
 PCS CFT



W5W TBA

**212-1419PXB-C**  
 SIDE LAMP  
 50PCS 0.92CFT




**312-1985**  
 TAIL LAMP  
 R 81550-52110  
 L 81560-52100  
 PCS CFT



WY21W/W21/5W/W21W TBA

REPLACEMENT FOR

**bB '06**



**212-11K4-RD-M**  
 HEAD LAMP  
 R  
 L 81150-B1140  
 PCS CFT




H4/W5W TBA



**212-1422**  
 SIDE LAMP  
 81730-B1010  
 PCS CFT



W5W TBA



**212-19N1**  
 TAIL LAMP  
 R  
 L 81560-B1060  
 PCS CFT



W16W/WY21W TBA

**212-19D4P-B-VCE**  
 TAIL LAMP  
 R  
 L  
 6PRS 4.85CFT



**212-19D4P-VCR**  
 TAIL LAMP  
 R  
 L  
 6PRS 4.85CFT



**TOYOTA**