

SAFARI '85-'94

REPLACEMENT FOR

332-1539PTB-VC
CORNER LAMP
10PRS 3.42CFT

OEM PARTS

332-1539R/L-US



TUNING PARTS

332-1539PTB-VC



12V5W/12V21/5W

332-1918P-B-VC
TAIL LAMP
5PRS 1.62CFT

OEM PARTS

332-1918R/L-US



TUNING PARTS

332-1918P-B-VC



12V21W/12V5W/12V21/5W

SAFARI '95-'02

REPLACEMENT FOR

332-1415PTU-VC
SIDE LAMP
50PRS 1.64CFT

OEM PARTS

332-1415



TUNING PARTS

332-1415PTU-VC

