



REPLACEMENT FOR
SEPHIA '96



REPLACEMENT FOR
SEPHIA '98-

223-1103

HEAD LAMP

R

L

PCS CFT



H4/H3

TBA

223-1109-LD

HEAD LAMP

R OK2A1-51-010

R OK2A1-51-030

L OK2A1-51-020

L OK2A1-51-040

4PCS

4.26CFT



H4/PY21W/W5W

223-1503

CORNER LAMP

R

L

PCS CFT



TBA

223-1908

TAIL LAMP

R

L

PCS CFT



TBA

223-1601

FRONT LAMP

R OK240-51-060A

L OK240-51-070A

PCS CFT



PY21W

TBA

223-1401N

SIDE LAMP

PCS CFT



TBA

223-1902

TAIL LAMP

R

L

PCS CFT



TBA



KIA