



REPLACEMENT FOR

LUPU '98-'01



REPLACEMENT FOR

LUPU '02

441-1135-LDEM1

HEAD LAMP
R 6X1941752F
L 6X1941751F
4PCS 4.15CFT



H4/W5W

441-1135-LDEM2

HEAD LAMP
R
L
4PCS 4.15CFT



H4/W5W

441-1155-LD

HEAD LAMP
R 6E1-941-754-B
L 6E1-941-753-B
PCS CFT



HID/W5W

TBA

445-2002-UE

FOG LAMP
R 6H0-941-700
L 6H0-941-699
24PCS 2.69CFT



H3

441-1618

FRONT LAMP
R
L
PCS CFT



TBA

441-1406N-UE-Y

SIDE LAMP
100PCS 0.90CFT



W5W

441-1938

TAIL LAMP
R
L
PCS CFT



TBA

441-1406N-UE-C

SIDE LAMP
100PCS 0.90CFT



WY5W

441-1406N-UE-S

SIDE LAMP
100PCS 0.90CFT



W5W